
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S06I007MH	Test ID: <u>D1032-007009</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S06I016MH
0			Start of Survey	
0			Water Level	
141.6000061	09		Tap Factory Active	
141.6000061			Dye Test Visible	DYE SEEN IN TAP
146.6000061			Dye Test Visible	DYE SEEN AT JOINT
149.6000061			Dye Test Visible	DYE SEEN AT JOINT
152.8000031			Dye Test Visible	DYE SEEN AT JOINT
155.8000031			Dye Test Visible	DYE SEEN AT JOINT
158.8999939			Dye Test Visible	DYE SEEN AT JOINT
188.6999969			Abandoned Survey	DYE TEST IS COMPLETE

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp □ Wet □	Supervisor: JAW
Manhole_ID: S06I007MH	Test ID: <u>D1032-007009</u>	Notification Made: NA (Residents, Fire, 311)